



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor


Robert L. Morgan
Executive Director

Lowell P. Braxton
Division Director



1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

July 30, 2003

TO: Minerals File

FROM: Tom Munson, Senior Reclamation Hydrologist 

SUBJECT: Site Inspection, H.E. Davis Construction, Levan Henry 1 & 2 Mine, M/023/023, Juab County, Utah

Date of Inspection: July 16, 2003
Time of Inspection: 12:00 – 1:00 p.m.
Conditions: Sunny  
Participants: Tom Munson and Doug Jensen, DOGM

Purpose of Inspection:

To confirm the amount of waste dump that occurs within private and federal lands and also to determine if the bond that the U.S. Forest Service holds is adequate to reclaim the large mine site.

Observations:

Doug Jensen GPS'd the waste dump and pad at 3.76 acres. There is an access road which, although it shows on the Chris Canyon quadrangle map, is an access road of approximately 3,185 feet averaging 25 feet wide to access the site.

The mine is in the very steep slot canyon. The mining is restricted by the high canyon walls. The operation has a crusher set up and is mining material from the slot and crushing more material on site. They were actively pursuing this project at the time of our inspection.

Conclusions and Recommendations:

Two things need to occur:

1) The Division needs to verify what the current land ownership is. I called Brian McClelland of the Ferron District Forest Service, requesting a map that shows forest boundaries in the area of the mine so that we can calculate or approximate how much area is disturbed on private land vs. Forest Service land.

Site Inspection

Page 2 of 2

M/023/023

Inspection Date: July 16, 2003 – Report date: July 30, 2003

2) H.E. Davis needs to resubmit a new mine and reclamation plan which shows all current and planned disturbances, so the Division can verify if the bond money currently being held by the Forest Service is adequate.

jb

Attachment: GPS map


cc: Kay Christofferson, H.E. Davis w/map


O:\M023-Juab\M0230023-Henry 1&2\inspections\insp-07162003.doc

H.E. Davis Henry 1 and 2 Mine M023/023



500 0 500 1000 1500 Feet

 Waste and Pad - 3.76 Acres
Access Road - 3185 feet long




Location: T 15 S., R 1 E., Sec. 19
USGS Quad : Chris Canyon
Inspection Date: July 16, 2003
People Participating: Doug Jensen
and Tom Munson, DOGM

This product may not meet DOGM
standards for accuracy and content.
Different data sources and input scales
may cause some misalignment of Data
layers.


H.E. Davis

Henry 1 and 2 Mine

M023/023



 Waste and Pad - 3.76 Acres
Access Road - 3185 feet long



Location: T 15 S., R 1 E., Sec. 19
USGS Quad : Chris Canyon
Inspection Date: July 16, 2003
People Participating: Doug Jensen
and Tom Munson, DOGM

This product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause some misalignment of Data layers.